43/807

60175000 s53354b

Global Parts Order Processing Material Safety Data Sheet MORAN ST. CLAIR CHRYSLER JEEP

June 6, 2012 13:31

CHRYSLER HAZARD COMMUNICATION SHEET 93722 PART/COMMTY CD: 04318070 PREPARATION DATE: 05-04-04 STNDRD: N/AV SUPPLIER: 82377 MFGR: 03500 OSHA HAZ: YES HAZWOPER HAZ: YES CONS PROD/HAZ SUB: YES *** SECTION 01 - PRODUCT INFORMATION *** -----MFG BY: PART SALES & SERVICE CHRYSLER 26311 LAWRENCE AVE CENTERLINE MI 48015 AFTER HOURS: 248-576-8888 EMERGENCY PHONE: 248-512-8002 DIST BY: PART SALES & SERVICE CHRYSLER 26311 LAWRENCE AVE CENTERLINE MI 48015 EMERGENCY PHONE: 248-512-8002 AFTER HOURS: 248-576-8888 CHRYSLER INDUSTRIAL HYGIENE: 248-512-8260 AFTER HOURS: 248-576-8888 BRAND NAME: MOPAR SILICONE SPRAYLUBE MFG ID : PBRM03/041492 DESCRIPTION: LUBE-SILICONE SPRAY *** SECTION 02 - INGREDIENTS *** HAZARDOUS INGREDIENTS: PERCENT COMM NAME / CAS NO & CHEM NAME: BY WGT OSHA ACGIH CHRYS UNITS NOTATIONS ***EXISTING INGREDIENTS*** SOLVENT NAPHTHA (PETROLEUM), MEDI 60-100 W 400 N/AP 400 PPM 064742-88-7 SOLVENT NAPHTHA, PET PETROLEUM PRODUCTS, LIQUEFIED GAS 10-30 W 1000 1000 PPM 068476-86-8 PETROLEUM GASES, LIQ POLY (DIMETHYLSILOXANE) 5-10 W N/AP N/AP N/AP N/AP 063148-62-9 SILOXANES AND SILICO GENERIC DESC: GENERAL SILICONE LUBRICANT *** SECTION 03 - PHYSICAL DATA *** BOILING POINT : N/AV SOLUB IN WATER: NEGLIGIBLE (< 0.1%) VAPOR PRESSURE: >999 MM HG ATN/AV EVAP. RATE: N/AV REF: N/AV 0.790 AT N/AV VAPOR DENSITY : > 1.000 AT N/AV SPECIFIC GRAVITY: PH AT FULL STRENGTH: N/AV PH AT REC. DILUT: N/AV VOLATILE ORGANIC COMP: N/AV %VOLATILE BY VOL : > 65.0 N/AV N/AV PPM FOR ODOR THRESHOLD: % POPULATION FREEZING POINT: N/AV COEFF. OF WATER/OIL DIST: N/AV APPEARANCE & ODOR: APPEARANCE: CLEAR..... COLOR: COLORLESS..... STATE: LIQUID..... FORM: SPRAY OR AEROSOL..... ODOR: PETROLEUM..... *** SECTION 04 - FIRE AND EXPLOSION DATA *** FLASH POINT: 105 F TCC IGN TEMP: N/AV LEL: N/AV UEL: N/AV

Page 1 of 4

Global Parts Order Processing Material Safety Data Sheet MORAN ST. CLAIR CHRYSLER JEEP

, ,

SPECIAL FIRE & EXPLOSION HAZARDS: CONTENTS UNDER PRESSURE. MAY EXPLODE IF EXPOSED TO HEAT OR FLAME. REACTS ON CONTACT WITH OXIDIZERS. EXTINGUISHING MEDIA: FOAM, DRY CHEMICAL OR CARBON DIOXIDE. SPECIAL FIREFIGHTING PROCEDURES: AVOID BREATHING VAPOR OR FUMES. USE SELF-CONTAINED BREATHING APPARATUS. USE PROTECTIVE CLOTHING. USE WATER TO COOL FIRE EXPOSED CONTAINERS. SENSITIVE TO MECHANICAL IMPACT?: N/AV SENSITIVE TO STATIC DISCHARGE?: N/AV HAZARDOUS COMBUSTION PRODUCTS: OXIDES OF CARBON FLAME PROJECTION: > 18 IN ______ *** SECTION 05 - HEALTH HAZARD DATA *** EFFECTS OF OVEREXPOSURE - ACUTE & CHRONIC: <<---INHALATION--->> MIST WILL PRODUCE THE FOLLOWING: IRRITATION OF UPPER RESPIRATORY TRACT.. SYMPTOMS ARE MORE LIKELY TO OCCUR IN POORLY VENTILATED AREAS., HIGH CONCENTRATIONS-MAY CAUSE HEADACHE, NAUSEA, DIZZINESS AND VOMITING. <<---SKIN CONTACT--->> SKIN CONTACT MAY PRODUCE DEFATTING AND DRYING OF SKIN. COMPONENT(S) - MAY BE ABSORBED THROUGH SKIN. <<--- EYE CONTACT --->> DIRECT CONTACT MAY PRODUCE THE FOLLOWING: IRRITATION AND TEARING. <<---INGESTION--->> MAY BE HARMFUL OR FATAL IF SWALLOWED. EMERGENCY FIRST AID PROCEDURES: <<---INHALATION--->> REMOVE TO FRESH AIR AT ONCE. ARTIFICIAL RESPIRATION IF BREATHING HAS STOPPED. CARDIAC RESUSCITATION IF INDICATED. CONTACT A PHYSICIAN. <---SKIN CONTACT---> REMOVE CONTAMINATED CLOTHING. WASH WITH SOAP AND WATER. APPLY SKIN CREAM IF DEFATTING OF SKIN OCCURS. IF CONDITION PERSISTS, CONSULT A PHYSICIAN. <<---EYE CONTACT--->> RINSE EYES IMMEDIATELY WITH LARGE AMOUNTS OF WATER, OCCASIONALLY LIFTING BOTH UPPER AND LOWER LIDS. CONTINUE FOR 15 MINUTES, CONTACT A PHYSICIAN, <---INGESTION--->> DO NOT INDUCE VOMITING-CALL PHYSICIAN IMMEDIATELY. *** SECTION 06 - REACTIVITY DATA *** STABILITY: STABLE CONDITIONS TO AVOID: HIGH TEMPERATURE, SPARKS OR OPEN FLAME. HOT REACTIVE METALS. MATERIALS TO AVOID: STRONG OXIDIZING AGENTS-CHLORINE OR PURE OXYGEN. HAZARDOUS POLYMERIZATION: WILL NOT OCCUR POLYMERIZATION CONDITIONS TO AVOID: POLYMERIZATION WILL NOT OCCUR. HAZARDOUS DECOMPOSITION PRODUCTS: OXIDES OF CARBON *** SECTION 07 - SPILL OR LEAK PROCEDURES *** Page 2 of 4

Global Parts Order Processing Material Safety Data Sheet MORAN ST, CLAIR CHRYSLER JEEP

• 2

STEPS TO BE TAKEN IF MATERIAL IS RELEASED OR SPILLED: ELIMINATE ALL IGNITION SOURCES (FLAMES, HOT SURFACES AND ELECTRICAL, STATIC OR FRICTIONAL SPARKS). REMOVE PRESSURIZED CANS AND VENT IN A SAFE, WELL VENTILATED OPEN AREA. WIPE UP OR SCRAPE UP SMALL SPILL OR RESIDUE. WASTE DISPOSAL METHODS: DO NOT INCINERATE CLOSED CONTAINERS. DISPOSE OF IN A MANNER CONSISTENT WITH STATE, PROVINCIAL, LOCAL, AND FEDERAL REGULATIONS. *** SECTION 08 - SPECIAL PROTECTION *** RESPIRATORY PROTECTION: NO SPECIAL PROTECTION NEEDED UNDER NORMAL CONDITIONS. ORGANIC VAPOR RESPIRATOR OR SELF-CONTAINED BREATHING APPARATUS WITH A FULL FACEPIECE OPERATED IN PRESSURE-DEMAND OR OTHER POSITIVE PRESSURE MODE,. THIS EQUIPMENT MAY BE NEEDED IF THE ALLOWABLE LIMIT OF THE PRODUCT OR ANY COMPONENT IS EXCEEDED... VENTILATION TYPE: GOOD GENERAL VENTILATION AND/OR LOCAL EXHAUST VENTILATION. THIS EQUIPMENT MAY BE NEEDED TO MAINTAIN THE TLV.. PROTECTIVE GLOVES: FOR DIRECT SKIN CONTACT WITH PRODUCT USE THE FOLLOWING: BUTYL RUBBER GLOVES OR NEOPRENE GLOVES. EYE PROTECTION: RECOMMENDED. SAFETY GLASSES WITH SIDE SHIELDS OR FULL FACE SHIELD. OTHER PROTECTIVE EQUIPMENT: PREVENT PROLONGED SKIN CONTACT WITH CONTAMINATED CLOTHING. WASH CONTAMINATED CLOTHING BEFORE REUSE. *** SECTION 09 - SPECIAL PRECAUTIONS *** _____ PRECAUTIONS TO BE TAKEN IN HANDLING & STORAGE: CONTENTS ARE UNDER PRESSURE. STORE AT TEMPERATURE BELOW 120 F (49 C). KEEP FROM HEAT, SPARK OR OPEN FLAMES. TAKE "NO SMOKING" PRECAUTIONS. USE WITH ADEQUATE VENTILATION. REACTS WITH OXIDIZERS. AVOID MECHANICAL SHOCK. DO NOT PUNCTURE, DROP OR SLIDE CONTAINERS. COMBUSTIBLE. OTHER PRECAUTIONARY MEASURES: AVOID BREATHING MIST. AVOID EYE CONTACT. AVOID PROLONGED OR REPEATED SKIN CONTACT. AVOID INGESTION. DO NOT SMOKE OR EAT WHEN HANDLING THIS SUBSTANCE; WASH THOROUGHLY AFTER USING. REMOVE CONTAMINATED CLOTHING AND LAUNDER BEFORE REUSE. MAINTAIN GOOD HOUSEKEEPING AND HYGIENIC PRACTICES. *** SECTION 10 - WASTE LABELING INFORMATION *** ______ DOT LABELING INFORMATION (49 CFR 100-199) ID#: N/AP ERG#: 126 HAZARD CLASS ~ PRMY: ORM-D PACKING GROUP: N/AP PROPER SHIPPING NAME: WASTE CONSUMER COMMODITY Page 3 of 4

60175000 s53354b

Global Parts Order Processing Material Safety Data Sheet MORAN ST. CLAIR CHRYSLER JEEP

, . P

June 6, 2012 13:31

LABEL(S) REQUIRED: NONE RCRA INFORMATION (40 CFR 122-124, 260-265) WASTE CODE(S)/HZD: D001/I | MICH: THE ABOVE INFORMATION IS BASED ON DATA PROVIDED BY SUPPLIERS. TESTING IS NOT NEEDED